

Software version history

Released Version	Date	Description
V2.0 B365	February 2020	Supported model types: All X2/BoX2 extreme except SC (Soft Control) variant <b>NOTE!</b> Update of Image requires update of related EBOOT Build 365 as well. Update EBOOT via “Make Recovery SD Card”, see “Beijer Panel Image” manual (MA205x) for information.
V1.2.1 B287	July 2019	Supported model types: All X2/BoX2 extreme variant
V1.2 B283	June 2019	Supported model types: All X2/BoX2 extreme except SC (Soft Control) variant <b>NOTE!</b> Update of Image requires update of related EBOOT Build 166 as well. Update EBOOT via “Make Recovery SD Card”, see “Beijer Panel Image” manual (MA205x) for information.
V1.1 B166	May 2018	Supported model types: New: X2 extreme 7, X2 extreme 7 SL HP, X2 extreme 12 SL HP, X2 extreme 15 SL HP. X2 extreme 12, X2 extreme 15 X2 extreme 12 HP, X2 extreme 15 HP <b>NOTE!</b> Update of Image requires update of related EBOOT Build 166 as well. Update EBOOT via “Make Recovery SD Card”, see “Beijer Panel Image” manual (MA205x) for information.
v1.0 B118	November 2017	Initial release of the X2 extreme Sealed panel types. Supported model types: New: X2 extreme 7, X2 extreme 7 SL HP, X2 extreme 12 SL HP, X2 extreme 15 SL HP. X2 extreme 12, X2 extreme 15 X2 extreme 12 HP, X2 extreme 15 HP
v1.0 B117	October 2017	Initial release of the X2 extreme panel platform. Supported model types: X2 extreme 12, X2 extreme 15 X2 extreme 12 HP, X2 extreme 15 HP

New features, removed functionality and corrected defects

Version	New features/ Bug fix	ID (internal)	Description
V2.0 B365	New features	#47060	Acirro+
		#49889	Firmware upgrade to include Eboot and NKbin
	Removed		n/a
	Bug fixes	#48272	Improved SD card detection handling
		#48750	Solve the COM3 error on CAN2
		#49747	CPU temperature readings above 95 degrees read corrupt value
		#49896	Incorrect size report of eMMC driver
v.1.2.1 B287	New features	#47807	Change the naming of ethernet.
		#47534	No need to reflash of image if changing EtherCAT with DC to EtherCAT without DC.
	Removed		N/A
	Bug fixes	#46811	Fix SD-card writing issue.
V1.2 B283	New features	#38469, #46497	Add support for FTDI
	Removed		n/a
	Bug fixes	#38421, #46623, #46652	Improve touch functionality
		#46701	CPU throttle
		#46743, #46729	Improve backlight functionality
		#39265	Panel gets stuck in welcome screen (IPNAT)
		#46988	Improve mediaplayer performance
		#36652	Support of MPI Direct.

Release Notes:  
Software Image on **X2 extreme** panel series

v1.1 B166	New features	#38469	USB added to serial support by featuring an FTDI serial chip.
		#19547	CAN support Integrated.
		#33548	Rotation support displayed in bootloader.
	Removed		n/a
	Bug fixes		n/a
v1.0 B118	New features		Support of new panel types: X2 extreme 7, X2 extreme 7 SL HP, X2 extreme 12 SL HP, X2 extreme 15 SL HP.
	Removed		n/a
	Bug fixes		n/a
v1.0 B117	New features		Initial version
	Removed		n/a
	Bug fixes		n/a