

Known issues for X2 base v2**Build v1.01 B276**

All data are subject to change without notice.

| Known issues | ID (internal) | Description and comments |
|-----------------------------------|------------------|-------------------------------------------------------------------------|
| CPU frequency | #59637 | Reduced CPU frequency until adaptive temperature control is implemented |
| No support for Ethernet printer | #57156 | |
| No support for MPI direct | #53422 | |
| Slow graphic plotting performance | #22949 | Only occur when screen is rotated. |
| Randoms comm errors on LAN A. | 22861 | Error only occur if using MC protocol. |