

**Known issues for X2 base v2****Build v1.02 B280**

All data are subject to change without notice.

Known issues	ID (internal)	Description and comments
CPU frequency	#59637	Reduced CPU frequency until adaptive temperature control is implemented
No support for Ethernet printer	#57156	
No support for MPI direct	#53422	
Slow graphic plotting performance	#22949	Only occur when screen is rotated.
Randoms comm errors on LAN A.	#22861	Error only occur if using MC protocol.