

Known issues for X2 base v2**Build v1.1 B1015**

All data are subject to change without notice.

Known issues	ID (internal)	Description and comments
CPU frequency	#59637	Reduced CPU frequency on HP units until adaptive temperature control is implemented.
Slow graphic plotting performance	#22949	Only occur when screen is rotated.
Randoms comm errors on LAN A.	#22861	Error only occur if using MC (Melsec Communication) protocol.