

Known issues for X2 base v2

Build V2.2 B1041

All data are subject to change without notice.

| Known issues | ID (internal) | Description and comments |
|--|------------------|---|
| Print on share printer over ethernet | #69663 | Problem to print with PCL 5e Monochrome printer. |
| Display rotate issue on X2 base 15 v2 HP | #70656 | Display does not show complete pixel column when rotated 180 degrees |
| Can't downgrade boot to older builds | #70659 | Workaround exists. Downgrade first to previous released version. Then downgrade again to desired version. |
| CPU frequency | #59637 | Reduced CPU frequency on HP units until adaptive temperature control is implemented. |
| Slow graphic plotting performance | #22949 | Only occur when screen is rotated. |
| Randoms comm errors on LAN A. | #22861 | Error only occur if using MC (Melsec Communication) protocol. |