

## Main Features

- Bugfix release fixing several issues. This version will also support PLCnext systems.

## WebIQ Visuals

- WEBIQ-3972 Fix: Trend Widget: in certain circumstances scale settings were not retained
- WEBIQ-4009 Fix: IQ Alarm List: the filter at the bottom was not displayed correctly

## WebIQ Designer

- WEBIQ-3993 Fix: Layout Manager: exact positioning was not possible in the Hierarchy anymore using drag & drop
- WEBIQ-3998 Fix: Layout Manager: some keyboard shortcuts were not working anymore
- WEBIQ-4005 Fix: Layout Manager: localization dialog did not support keyboard shortcut Ctrl+V for pasting of text
- WEBIQ-4015 Fix: Layout Manager: when clicking on the "X" button in the item selection input in the Config tab to remove an item it was not really removed
- WEBIQ-4019 Fix: Layout Manager: performance improvement for complex multi-level panel HMIs in WebIQ Designer
- WEBIQ-4010 Fix: Package Manager: "Reload Packages" button did not return the user to the Package Manager, but the Layout Manager
- WEBIQ-3979 Fix: Process Data Manager: boolean items were imported with type 'boolean' instead of 'bool'
- WEBIQ-4034 Fix: Layout Manager: Possible errors when importing certain composites

## WebIQ Server

- WEBIQ-4022 Fix: Fixed a possible crash when unloading an HMI in certain rare circumstances
- WEBIQ-4018 Fix: "BadCertificateInvalid" error was returned when a client certificate with "keyCertSign" flag was used
- WEBIQ-4030 Fix: Process Data Manager: when the type of a recorded item changes the server crashed - usually only happened when changing the item type in WebIQ Designer.
- WEBIQ-4031 Fix: When the HMI cannot be loaded due to an error with the workspace WebIQ Designer loaded indefinitely because no error was returned
- WEBIQ-4020 Updated OpenSSL to version 3.1.4 - see <https://www.openssl.org/news/cl31.txt> for details
- WEBIQ-3967 Added support for PLCnext systems
- type 'watchdog' did not work anymore