

Main Features

- Bugfix release fixing several bugs.

WebIQ Server

- WEBIQ-4102 Added a workaround for ctrlX licenses where licenses with the same name might occur several times
- WEBIQ-4085 Added support for JavaScript modules (mjs) file format for sending the correct HTTP header to the client
- WEBIQ-4074 The simulation function 'alarmcount' now allows for specifying info/alarm/warning to get alarm counts by level
- WEBIQ-4060 Older HMIs before version 2.14 who used custom.sqlite will now be updated correctly
- WEBIQ-4089 Fix: Windows AD HMI authentication: the user's language setting was not transformed correctly
- WEBIQ-4087 Fix: Windows AD HMI authentication: username was not read correctly
- WEBIQ-4080 Fix: Recorder Manager: trigger/record events did not work correctly anymore
- WEBIQ-4077 Fix: The username was returned incorrectly and thus shown wrong in several widgets as well (esp. comments)
- WEBIQ-4065 Fix: Recipe Edit: dynamically configured item properties were not correctly reported
- WEBIQ-4033 Fix: On Linux when a recorder was listed in the .webiqignore file it was deleted on HMI upload instead of being ignored
- WEBIQ-4007 Fix: When using the simulation function 'randomramp' the minimum and maximum settings of the corresponding item were not honored correctly

WebIQ Designer

- WEBIQ-4093 Fix: Export of composites with associated icons/images that did not exist was not possible

WebIQ Visuals

- WEBIQ-4079 Fix: Recipe Edit: no or wrong units were shown in certain circumstances