

Known issues for X2 base v2**Build v1.0 B261**

All data are subject to change without notice.

Known issues	ID (internal)	Description and comments
No support for Ethernet printer	#57156	
No support for MPI direct	#53422	
Slow graphic plotting performance	#22949	Only occur when screen is rotated.
Randoms comm errors on LAN A.	22861	Error only occur if using MC protocol.