

**Known issues for X2 base v2****Build V2.3 B1103**

All data are subject to change without notice.

Known issues	ID (internal)	Description and comments
Print on share printer over ethernet	#69663	Problem to print with PCL 5e Monochrome printer.
Display rotate issue on X2 base 15 v2 HP	#70656	Display does not show complete pixel column when rotated 180 degrees
Can't downgrade boot to older builds	#70659	Workaround exists. Downgrade first to previous released version. Then downgrade again to desired version.
CPU frequency	#59637	Reduced CPU frequency on HP units until adaptive temperature control is implemented.
Slow graphic plotting performance	#22949	Only occur when screen is rotated.
Randoms comm errors on LAN A.	#22861	Error only occur if using MC (Melsec Communication) protocol.